

## Task Light Mounting Clamp Assembly

Part # WTLM

- 1 Insert upright clamps (A) and (B) into slotted uprights at desired position and attach using 5/16-18 x 1" hex head cap screws (C) (Fig - 1)

### Tool List

Ratchet with 1/2" socket, or  
impact wrench with 1/2" socket

Item	Components*	Qty
A	Upright clamp w/ mounting plate	1
B	Upright clamp w/ PEM fittings	1
C	5/16-18 x 1" Hex head cap screws	2




Fig - 1